



# 2-in-1 Digital AngleRule Instruction

## Technical Data:

Measuring Range: 000.0° ~ 999.9°  
(more than 999.9° incorrect display)  
Working Temperature: 0°C ~ +50°C  
Working Humid: ≤85%RH  
Working Current: ≤50μA  
(more than 5000 hours in continuous use)  
Resolution: 0.1°  
Accuracy: 0.3°  
Battery: CR2032 3V Lithium Battery




**ON/OFF button:** Short press ON/OFF to turn on 2-in-1. Short press ON/OFF to shut off the LCD. Long press ON/OFF for more than 3 seconds to shut off the whole system. Automatically shut off function in 6 min. Move the scale to turn on the device when at off LCD status.




**ZERO button:** Press ZERO to set zero at any point when turn on 2-in-1.

## Operating Instruction:

Rotate clockwise to tighten the moving ruler;  
Rotate counterclockwise to loosen the moving ruler.




Short press ON/OFF to turn it on, put it on the flat surface as pic, make sure the both ruler's edges touch the surface, press ZERO button to set zero.




## Battery:


- To replace battery, push the protrusion on the bottom of the LCD, the edge of battery container appears on the upper side of the LCD. (Pic 1).
- Pull the battery container out (Pic 2).
- The negative pole of battery is upside, positive pole is downwards. (Pic 3).
- Push the battery container back in. (Pic 4).




Pic 1



Pic 2



Pic 3



Pic 4

## Trouble Shooting:

Problem	Possible Cause	Solution
No display or ambiguous	Lower voltage, no battery or incorrect installation of battery	Reinstall battery or replace battery
Erratic display	Casual Misfunction Caused by High Vibration or Strongly Swinging	Zero setting
Number skip or frozen display	Internal error	Remove battery wait 1 minute and replace